

C.H. Bradshaw Co.
2004 Hendrix Drive
Grove City, Ohio 43123-1278
DOT CT0097

(VKE) REVISION 11/21

Work Order # 097142

V
K
K-EPA 27

External Visual Inspection
Leakage Test / Inspection
Annual Certification Test
Method 27 - 63.425 (e) (1) (2)

Customer SSA Transport Inc.
Address 101 E. South St
C.S.Z. Rockford, Ohio 45882

Owner Same

License Plate # TPN 8329
Owners Unit # 75
Serial # 5HTAM442217H65438
Trlr. Vin # (If Applicable) 5HTAM442217H65438
D.O.T. Spec # DOT 406 AL
Original Test Date 01-01
Design or MAWP 3.3
Test Location (C.S.) Rockford, Ohio

Previous Test Dates
V 4-23
I 4-21
P 4-21
K 4-23
K-EPA.27 4-23
Number of Compartments 4

Compartment Size: #1 3500 #2 1000 #3 2000 #4 2700 #5 X

Year Tank Mfg. 01-01 Mfg. Name Heil Trailer Gallons 9200

Minimum Thickness Of Cargo Tank Shell .173 Heads .173

Is Tank Lined? no Insulated? no

Is the unit used for transport of any material other than petroleum based products? no

External Visual Inspection 180.407 (d)

	Faulty	Okay
1.) External Inspection Of Tank Shell And Heads:		
A) Corroded or Abraded Areas (Rust)	---	<u>/</u>
B) Dents or Punctures	---	<u>/</u>
C) Distortion or Defects In Welds	---	<u>/</u>
D) Thickness Testing Needed	---	<u>/</u>
E) Tank has Imaging Decals (Wrap)	YES	<u>NO</u>
Internal Visual In Accordance To 180.407(c)	YES	<u>NO</u>
2.) External Inspection Of Piping, Valves, Gaskets:		
A) Corroded Areas	---	<u>/</u>
B) Defects in Welds, Signs of Leakage	---	<u>/</u>
C) Condition of delivery, vapor hoses	---	<u>/</u>

	Faulty	Okay
3) External Inspection Of Manholes:		
A) Devices for tightening manhole covers operative	___	___/
B) Evidence of leakage	___	___/
C) Inspect and pressure test fill lids, normal vents	___	___/
4) External Inspection Of Emergency Valves And Devices		
A) Emergency valves free from corrosion, erosion, distortion, or external damage that would prevent safe operation	___	___/
B) Remote trip control in operation / activate	___	___/
C) Leakage test seating disc in emergency valve	___	___/
D) Self closing stop valves in operation - function	___	___/
5) <u>Missing</u> bolts, nuts, and fusible links must be replaced and loose nuts - bolts tightened	___	___/
6) All Required Marking On Tank Legible		
A) DOT spec. plate accessible / legible	___	___/
B) Flammable placards legible (all 4-sides)	___	___/
7) External Inspection Of All Major Appurtenances		
A) Fifth wheel plate, pins, bolts	___	___/
B) Suspension, springs, hangers, etc.	___	___/
C) Frame, cross members, gussets, etc.	___	___/
8) Inspect all re-closing pressure relief valves	___	___/
9) Lights, reflectors, wiring in good working order	___	___/
10) Brakes in good working order	___	___/
11) Air hoses above axles, chambers, chafed, or rotted	___	___/
12) Air system have any leaks	___	___/
13) Tank mounting bolts, boards, attachments in proper working order	___	___/
14) Leakage test entire pump system(s)	<u>N/A</u>	<u>N/A</u>

(VKE) REVISION 11/21 (pg3)

Work Order # 097142

Leakage Test 180.407 (h) Pneumatic

Each cargo tank with all valves and accessories in place or operative must be tested at not less than 80% of the tank design pressure or maximum allowable working pressure (MAWP) whichever is marked on the certification plate.

Compt.	#1	#2	#3	#4	#5	#6
Start Time	<u>7:19</u>	<u>7:27</u>	<u>7:13</u>	<u>7:34</u>	<u> </u>	<u> </u>
Pressure	<u>2.6</u>	<u>2.6</u>	<u>2.6</u>	<u>2.6</u>	<u> </u>	<u> </u>
Final Time	<u>7:24</u>	<u>7:32</u>	<u>7:18</u>	<u>7:39</u>	<u> </u>	<u> </u>

Alternate EPA / Pressure Vacuum Test Method 27 / 40CFR63.425

Pressure Test = 18"

Test	1 Minute	2 Minutes	3 Minutes	4 Minutes	5 Minutes	Time
1	<u>18.0</u>	<u>18.0</u>	<u>18.0</u>	<u>18.0</u>	<u>18.0</u>	<u>7:42 AM</u>
2	<u>18.0</u>	<u>18.0</u>	<u>18.0</u>	<u>18.0</u>	<u>18.0</u>	<u>Average</u>
						<u>18.0"</u>

Vacuum Test = -6.0"

Test	1 Minute	2 Minutes	3 Minutes	4 Minutes	5 Minutes	Time
1	<u>-5.9</u>	<u>-5.8</u>	<u>-5.7</u>	<u>-5.7</u>	<u>-5.6</u>	<u>7:57 AM</u>
2	<u>-6.0</u>	<u>-5.9</u>	<u>-5.8</u>	<u>-5.7</u>	<u>-5.6</u>	<u>Average</u>
						<u>-5.6"</u>

Vapor Vent Test/Vapor Rail Pressure Test

Test	1 Minute	2 Minutes	3 Minutes	4 Minutes	5 Minutes	Time
1	<u>0"</u>	<u>0.1"</u>	<u>0.1"</u>	<u>0.2"</u>	<u>0.2"</u>	<u>8:11 AM</u>
2						

Location of Defects Found and Method of Repair:

- 1.) _____
- 2.) _____
- 3.) _____
- 4.) _____
- 5.) _____

Attach Supplemental Sheets For Information Or Supporting Test Papers

Cargo Tank Meets The Requirements Of The DOT Specification

Identified On This Report Yes No

Was The Tank Marked

"V"	<u>YES</u>	Month <u>4</u>	Year <u>24</u>
"K"	<u>YES</u>	Month <u>4</u>	Year <u>24</u>
"K" EPA	<u>YES</u>	Month <u>4</u>	Year <u>24</u>
"T"	<u> </u>	Month <u> </u>	Year <u> </u>

I certify that the above inspections were conducted in accordance with 180.407.

Owner Acknowledgment Robert W. Bush Date 4-22-24
 R/I, Manager's Acknowledgment [Signature] Date 4-22-24
 Inspected By: T. Bush Print TIM BUSH Date 4-22-24



Energy Transfer Partners
 Data Operations and
 Carrier Compliance
 4041 Market Street
 Aston, PA 19014
 Version 1.1 - 08/03/2020

WET TEST CERTIFICATION FORM

This document certifies that this trailer testing has been completed and has passed the wet test requirement for overfill protection probes. This certifies that the entire operation of the truck overfill prevention system is wired correctly and that the entire system is working properly.

The trailer noted below meets the requirements for the overfill probes to be set where the maximum safe fill is at least sixty (60) gallons less than the manufacturers specified compartment capacity.

PROBES TESTED AND SET PROPERLY

	YES	NO	SAFE FILL AMOUNT (GALS)
Compartment #1:	✓		3500
Compartment #2:	✓		1000
Compartment #3:	✓		2000
Compartment #4:	✓		2700
Compartment #5:	N/A		
Compartment #6:	N/A		

Carrier Name: SSA TRANSPORT

Carrier Address: 101 E SOUTH ST.
ROCKFORD, OH 45882

Trailer Number: 75

VIN Number: SHTAM 442217HGS 438

Signature: Tim B...

Date: 4/22/24



CITGO Petroleum Corporation
TERMINALS AND PIPELINES

Carrier Equipment Inspection Form	TPL-OPS-002-C
Effective Date: June 15, 2020	Rev. 0

Carrier Name: SJA TRANSPORT Trailer Unit #: 75
 Trailer: Make HEIL Year 2001 DOT Type 406 Serial Number SJAM 442217H65438
 Retain Sensors Installed Yes No

API RP 1004: Bottom Loading and Vapor Recovery for MC-306 & DOT-406 Tank Motor Vehicles

	Example	Front Compartments					
		#1	#2	#3	#4	#5	#6
1 Max Compartment Capacity	3140	3581	1122	2103	2772		
2 Probe Outage (60 gal min)	60	60	60	60			
3 *Carrier Outage	80	3521	1062	2043	2712		
4 Maximum Preset	3000	3500	1000	2000	2700	—	—

Subtract Lines 2&3 from Line 1

All Sections must be completed

*Carrier outage is the distance between the overfill probe and the product that prevents setting off the rack shutdown system (domeouts). This option is at the discretion of the carrier and varies on the tank strapping charts and the level outage selected.

Certified Inspection Requirements

All Boxes Must Be Completed

	YES
1 Has the overfill protection probe been set & tested to a minimum of 60 gross gallons below the maximum compartment capacity?	<input checked="" type="checkbox"/>
2 Is the overfill protection system in working condition?	<input checked="" type="checkbox"/>
3 Has each compartments probe been tested with liquid to verify that it activates the shutdown circuitry?	<input checked="" type="checkbox"/>
4 Has the grounding system been checked and is in proper operating condition?	<input checked="" type="checkbox"/>
5 Has the grounding system been checked to ensure that has not been modified or rewired in any manner that would allow it to provide a false reading to allow loading?	<input checked="" type="checkbox"/>
6 Are all gauge rods and any other compartment protrusions properly grounded with secure bonding wires?	<input checked="" type="checkbox"/>
7 Is a functional brake interlock system installed on the loading header and vapor recovery hose?	<input checked="" type="checkbox"/>

TIM BUCK
Name (Print)

C.H. BRADSHAW
Inspection Company

4/22/24
Date (MM/DD/YY)

[Signature]
Name (Sign)

CT00 97
Inspector's DOT reg. #

Carrier Verification Requirements

	YES
1 Is an MC306 DOT406 or other specification plate installed?	<input checked="" type="checkbox"/>
2 Is proper placarding installed for the product(s) that are hauled?	<input checked="" type="checkbox"/>
3 Is the state DOT inspection or DOT 396/17 data current?	<input checked="" type="checkbox"/>
4 Are pressure, leakage and visual decals current?	<input checked="" type="checkbox"/>
5 Is emergency response information (including guidebook) on board?	<input checked="" type="checkbox"/>
6 Is each tank/trailer marked with appropriate unit numbers?	<input checked="" type="checkbox"/>
7 Are compartment capacity charts current and available upon request?	<input checked="" type="checkbox"/>
8 Is each compartment loading headers matching with maximum presets recorded above?	<input checked="" type="checkbox"/>

As representative of the company, I certify that all information on this document is certified and true.

ROBERT BEWA Robert Bewa PRESIDENT
Name (Print & Sign) Title

4/22/24
Date (MM/DD/YY)